

AI - VI - A - 009
Old Wilson Brick Farm House
Pinto

1860

This typical old brick farmhouse is of rectangular construction with a side wing off the south side. The original main entrance has been moved from the eastern side to the rear western end, and the three bay end porch which covered the original entrance has been since torn down. At the present the main entrance is covered by a three bay end porch with sled roof. The roof of the main facade is gabled, and three flush end chimneys rise from there.

MARYLAND HISTORICAL TRUST

0102535535
AL-VI-A-009

INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

1 NAME

HISTORIC

Wilson Brick Farm House

AND/OR COMMON

Shumaker Farm

2 LOCATION

STREET & NUMBER

Rt. 220 South, 1.3 miles South of Rt. 9

CITY, TOWN

Pinto

☒ VICINITY OF

CONGRESSIONAL DISTRICT

Sixth

STATE

Maryland

COUNTY

Allegany

3 CLASSIFICATION

CATEGORY

☐ DISTRICT

☒ BUILDING(S)

☐ STRUCTURE

☐ SITE

☐ OBJECT

OWNERSHIP

☐ PUBLIC

☒ PRIVATE

☐ BOTH

PUBLIC ACQUISITION

☐ IN PROCESS

☐ BEING CONSIDERED

STATUS

☒ OCCUPIED

☐ UNOCCUPIED

☐ WORK IN PROGRESS

ACCESSIBLE

☐ YES: RESTRICTED

☐ YES: UNRESTRICTED

☒ NO

PRESENT USE

☒ AGRICULTURE

☐ COMMERCIAL

☐ EDUCATIONAL

☐ ENTERTAINMENT

☐ GOVERNMENT

☐ INDUSTRIAL

☐ MILITARY

☐ MUSEUM

☐ PARK

☒ PRIVATE RESIDENCE

☐ RELIGIOUS

☐ SCIENTIFIC

☐ TRANSPORTATION

☐ OTHER:

4 OWNER OF PROPERTY

NAME

William & John Shumaker

Telephone #: 729-3576

STREET & NUMBER

Rt. 6 Box 197

CITY, TOWN

Cumberland

☐ VICINITY OF

STATE, zip code
Maryland 21502

5 LOCATION OF LEGAL DESCRIPTION

COURTHOUSE,

REGISTRY OF DEEDS, ETC. Allegany County Courthouse

Liber #: 252

Folio #: 113

STREET & NUMBER

30 Washington Street

CITY, TOWN

Cumberland

STATE
Maryland

6 REPRESENTATION IN EXISTING SURVEYS

TITLE

DATE

☐ FEDERAL ☐ STATE ☐ COUNTY ☐ LOCAL

DEPOSITORY FOR
SURVEY RECORDS

CITY, TOWN

STATE

7 DESCRIPTION

AL-VI-A-0089

CONDITION☐ EXCELLENT☒ GOOD☐ FAIR☐ DETERIORATED☐ RUINS☐ UNEXPOSED**CHECK ONE**☐ UNALTERED☒ ALTERED**CHECK ONE**☒ ORIGINAL SITE☐ MOVED DATE _____**DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE**

The Wilson brick farm house is located along Route 220 South past Pinto, Allegany County on the east side of the road one and three tenths miles South of Route 9.

The old farm house consists of a two story, three bay wide rectangular main facade. A lower two story wing and adjacent one story frame wing abut the main block on the southern side. The building is a brick structure laid in American common bond construction and is supported by a low stone foundation with a plain water table. The roof of the main facade as well as the wing is gabled and covered with replaced asphalt shingles. Windows in the building include double hung wooden sash frames with six-over-six lights, jack arch and plain trim. The main entrance is located on the rear western side and exhibits the original verticle paneled door with plain trim. A three bay end porch with shed roof covers the main entrance and it is supported by square columns. The original main entrance was located on the front eastern face and was covered by a three bay end porch. However, since construction, the end porch has been torn down and the main entrance door boarded. Three corbeled brick chimneys, which appear to be original, are located on the flush ends of the house; two on the main facade and one on the side wing.

The farm house is structurally very sound and retains most of its original appearance except for the replaced roofing materials and the absence of the front entrance and porch.

CONTINUE ON SEPARATE SHEET IF NECESSARY

PERIOD

REHISTORIC
 —1400-1499
 —1500-1599
 —1600-1699
 —1700-1799
 X1800-1899
 —1900-

—ARCHEOLOGY-PREHISTORIC
 —ARCHEOLOGY-HISTORIC
 —AGRICULTURE
 XARCHITECTURE
 —ART
 —COMMERCE
 —COMMUNICATIONS

AREAS OF SIGNIFICANCE -- CHECK AND JUSTIFY BELOW

—COMMUNITY PLANNING
 —CONSERVATION
 —ECONOMICS
 —EDUCATION
 —ENGINEERING
 —EXPLORATION/SETTLEMENT
 —INDUSTRY
 —INVENTION

—LANDSCAPE ARCHITECTURE
 —LAW
 —LITERATURE
 —MILITARY
 —MUSIC
 —PHILOSOPHY
 —POLITICS/GOVERNMENT

—RELIGION
 —SCIENCE
 —SCULPTURE
 —SOCIAL/HUMANITARIAN
 —THEATER
 —TRANSPORTATION
 —OTHER (SPECIFY)

SPECIFIC DATES 1860

BUILDER/ARCHITECT

STATEMENT OF SIGNIFICANCE

The Wilson Farm house was built in 1860 in all probability by John Welch. The building is a substantial one typical of other farmhouses built in Allegany County in the first half of the 19th century of special importance is the original spring house which still stands on the property. Signatures and dates written on the front eastern face mortar by children of the early inhabitants indicate that the house was built around 1860 and the comparison of this house with others along the Potomac River Valley also indicate this time period. This and the other larger farms in the valley were constructed here because of the beautiful scenery as well as the abundance of water and fertile soil found here.

The house is in good condition and certainly enhances the architectural heritage of the rural areas in Allegany County.

CONTINUE ON SEPARATE SHEET IF NECESSARY

AL-VIA-0089

9 MAJOR BIBLIOGRAPHICAL REFERENCES

Allegany County Land Records, Cumberland, Maryland

CONTINUE ON SEPARATE SHEET IF NECESSARY

10 GEOGRAPHICAL DATA

ACREAGE OF NOMINATED PROPERTY 11 acres

VERBAL BOUNDARY DESCRIPTION

LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES

STATE	COUNTY
STATE	COUNTY

11 FORM PREPARED BY

NAME / TITLE	John E. Nelson, Program Coordinator of All. Co. Historic Sites
ORGANIZATION	Allegany County Historic Sites Survey
STREET & NUMBER	10 Park Lane
CITY OR TOWN	Frostburg
DATE	7/6/76
TELEPHONE	689-8486
STATE	Maryland

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust
The Shaw House, 21 State Circle
Annapolis, Maryland 21401
(301) 267-1438

Old Wilson Brick Farm House
Route 220 South, 1.3 Miles South of Route 9

AL-VI-A-009

HISTORICAL CHAIN OF TITLE

Allegany County Deed - Liber 252, Folio 113
grantee: William and John Shumaker
grantor: John F. Lease
July 25, 1953

Allegany County Deed - Liber 223, Folio 211
grantee: John F. Lease
grantor: Vernon C. Liller
October 25, 1948

Allegany County Deed - Liber 222, Folio 669
grantee: Vernon C. Liller
grantor: C. A. Jewell and Paul J. Davis
September 16, 1948

Allegany County Deed - Liber 205, Folio 634
grantee: C. A. Jewell and Paul J. Davis
grantor: Charles S. Hansel
October 20, 1945

Allegany County Deed - Liber 146, Folio 667
grantee: Charles S. Hansel
grantor: Charles F. Shank
April 26, 1924

Allegany County Deed - Liber 132, Folio 246
grantee: Charles F. Shank
grantor: Robert C. and Aleinda P. Wilson
March 24, 1920

Allegany County Deed - Liber 112, Folio 27
grantee: Robert C. Wilson
grantor: Izora and George Robison
January 24, 1913

Allegany County Deed - Liber 103, Folio 567
grantee: Izora and George Robison
grantor: The Real Estate and Securities Company of Allegany County
September 10, 1908

Allegany County Deed - Liber 101, Folio 169
grantee: The Real Estate and Securities Company of Allegany County
grantor: Joseph Cadwallader
October 12, 1904

Allegany County Deed - Liber 65, Folio 334
grantee: Joseph Cadwallader and Mary Cadwallader
grantor: Mary and Philip Bier
August 23, 1888

Old Wilson Brick Farm House
Route 220 South, 1.3 Miles South of Route 9

AL-VI-A.009

HISTORICAL CHAIN OF TITLE

Allegany County Deed - Liber 60, Folio 318

grantee: Biers

grantor: Kate S. Lee

October 15, 1883

Allegany County Mortgage Liber 55, Folio 244

grantee: Kate S. Lee

grantor: William, Virginia and Rebecca Welch

June 21, 1881

Allegany County Deed - Liber 41, Folio 659

grantee: William Welch

grantor: John Welch and Rebecca Welch

March 7, 1874

Allegany County Deed - Liber 15, Folio 590

grantee: John Welch and Rebecca Welch

grantor: Elizabeth Welch

1857

INVENTORY NO.

A1-VI-A-009

Liber-252

Folio - 113

DATE:

6/15/76

- REMOINING: Drastic, moderate, minor Micheal Acres - ~~11~~ 11

NAME OF PROPERTY:

Old Wilson Brick Farm House

LOCATION OF PROPERTY:

1.3 Miles South of Rt. 9 Along Rt 220 South

DIRECTION DWELLING FACES:

~~West~~ East

NAME OF OWNER:

William E. Shumaker + John G. Shumaker

ADDRESS:

Rt. 6

Box 197

729-3576

Cumberland, MD. 21502

STORIES: 1() 2(✓) 3() 4() 5() 6() BAYS: 1() 2() 3(✓) 4() 5() 6() 7() ()

WINGS, ADDITIONS: Side Wing - South Side

Dwelling Shape: (square, cross, rectangular)

WALL CONSTRUCTION:

- () FRAME: Bevel, clapboard, weatherboard, wood shingles, board & batten (type?)
(✓) BRICK: Bond type- common, English, Flemish. Sketch variants.
() STONE: Bond type- rubble, ashlar (random or regular), quoins-plain, rusticated
() ICG
() Other: Coverings

WALL FEATURES: BELT COURSE, PILASTERS, OTHERS

PlainFOUNDATIONS: HIGH, LOW, BRICK, STONEWATER TABLE: NONE, PLAIN, BEVELLED, MOULDED BRICKWINDOWS, TRIM, SHUTTERS: 1/1() 2/2() 6/6(✓) 9/6() 9/9() other() Brick
pegged () nailed () wide () narrow () mitred () pediment (✓)

ENTRANCE, DOORS:

LOCATION: West East

HARDWARE: original(✓) replaced()

FAN LIGHT, TRANSOM, SIDE LIGHTS, PLAINPaneled, Verticle, Horizontal BoardsCORNICHE, BARGE, EAVES: (crown, fascia, soffit, bed)

original(✓) replaced() Rafter Ends, Modillions, Dentils, Frieze,

Architrave

ROOF: GABLE FRONT, GABLE FLANK, HIP, SHED, MANSARD, GAMBREL, FLAT, BORMERS #MATERIAL: wood shingles, slate, tin, asphalt original() replaced(✓)PORCHES: SHAPE OF ROOF - shed(✓) hip() gable() Bay EndCHIMNEYS: NUMBER 3 BRICK(✓) STONE() CORBELLED(✓) original(✓) replaced()LOCATION: Flush end(✓) Inside end() Outside end() Central() Interior()ARCHES: Door and window: Keystone, Flat, Segmental, Semicircular

COMMENTS:

Use - ResidenceSignificance - Arch.Date Constructed - 1860Condition - Fair - Good

Key points regarding interior architecture.

1. Floor plan

No through hall--How many rooms long and deep?
Where is stairway? Straight or winding?

With through hall--Rooms on both sides? How many?

Rooms on one side only? How many?

Is stair in through hall?

Open or enclosed? Straight--one run. Straight--landing

How many? Curved.

If not in hall, where is stair?

2. Wall finish: plaster, paneled, board partition
Note presence of chair rail, cornice, etc.

3. Fireplaces: How many? Parallel to walls or diagonal in corner?


Mantels: wood--mouldings, pilasters, columns
masonry--marble(what color?), brick

3. Doors: on the inside of exterior doors, note the presence of applied flush boards and their direction (diagonal, vertical, horizontal). In general are doors paneled or ledge or other?

4. Door and window trim: plain, architrave; fluted, reeded; pilasters

5. Kitchen: Where is original if extant or known (marked by very large fireplace)? Separate building; wing to principal dwelling; within principal dwelling? On which floor of any of the above?

6. Are there any other points of interest? (e.g., any wooden beams, etc.)



AI-VI-A-009
Wilson Brick Farm House
Rt. 220 South
USGS Cresaptown Quad
1:24,000
1949



Old Wilson Brick Farm House

AI-UI-A-009

Rt. 220 South

1.3 Miles S. of Rt. 9

John E. Nelson

6/15/76

North



Old Wilson Farm - Outbuilding
Springhouse

AI-UI-A-009


Rt. 220 South

1.3 Miles S. of Rt. 9

John E. Nelson

6/15/76

Southwest



Old Wilson Brick Farm House

Al-UL-A-009

Rt. 220 South

1.3 Miles S. of Rt. 9

John E. Nelson

6/15/76

East